


1084
1085
1082

EB 20039



FOR FREQUENCIES SEE MODULE FRONT PANEL LAYOUTS

- 1084 HAS SMOOTH CONTROLS REPLACES 1073
HAS SWITCHED HF
- 1085 HAS STEPPED CONTROLS REPLACES 1076
HAS SWITCHED HF
- 1082 SIMILAR TO 1084
HAS 30HZ INSTEAD OF 45HZ ON HPF
HAS ALL POT. DESIGNATIONS INVERTED

FOR 1084 SEE DRAWING ML 60598
 1085 ———
 1082 ——— ML 60555

Contributed by TerranceDwyer.com

		This drawing is the property of this company and may not be reproduced or disclosed to a third party without the permission of this company.	DATE 17 OCT 72
TITLE CHANNEL AMPLIFIERS 1084, 1085, 1082			DRAWING NUMBER EB 20039